

Detailed Qualifying List

Date Printed: 8/2/2017 10:07:01 AM

TONER CARTRIDGES

BROTHER

Part #	Value
BROTHER 4.00	\$1.80
BROTHER DR-720/DR-3300	\$2.70
BROTHER TN-720/TN-3330	\$1.80
BROTHER TN-750/TN-3380 MFC-8510DW/8710DW/8910DW/8950DTW/8950DW/DCP-8110DN/8150DN/8155DN/HL-5440D/5450DN/5470DW/5470DWT/HL-6180DW/6180DWT	\$1.80
BROTHER TN-780	\$1.80

HP

Part #	Value
HP 4014/4015/4515 RM1-4554	\$1.00
HP 80X CF280X	\$2.70
HP CC364A SERIES P4014/P4015/P4515	\$1.35
HP CC364X SERIES P4015/P4515	\$2.70
HP CE255X SERIES P3015 HIGH YIELD	\$2.25
HP CE390A LASERJET M4555 MFP/ENTERPRISE 600 SERIES M601/M602/M603	\$1.35
HP CE390X LASERJET M4555 MFP/ENTERPRISE 600 SERIES M601/M602/M603	\$2.70
HP CE505X SERIES P2055	\$2.70
HP CE742A SERIES 5225 YELLOW	\$1.80
HP CE743A SERIES 5225 MAGENTA	\$1.80
HP CF226A	\$2.70
HP CF226X	\$3.60
HP COLOR LASER JET 4700 / 4730MFP TRANSFER KIT PREMIUM (Q7504A) RM1-3161 & RM1-1708 & RM1-2149	\$1.00
HP CP2025 FUSER ASSY	\$1.00
HP LASERJET 4250/4350 RM1-1082	\$1.00
HP LASERJET P3015 RM1-6274	\$1.00
HP M401DN FUSING ASSEMBLY, FOR 110-127VAC	\$1.00
HP M4555/M4559 FUSER ASSY	\$1.00
HP M600 FUSER RM1-8395	\$1.00
HP M712 - FUSER ASSEMBLY	\$1.00
HP P2035/P2055 FUSER CORE	\$1.00
HP Q1338A SERIES 4200	\$5.63

INKJET PRINTER CARTRIDGES

CANON

Part #	Value
CANON 0618B002	\$0.45
CANON CL-211 COLOR HIGH YIELD 2975B001	\$1.35
CANON CL-241 COLOR 5209B001 5208B001	\$1.13
CANON CL-241XL COLOR 5208B001	\$1.58
CANON CL-246XL (8280B001) COLOR PIXMA MG3520/MG2420/MG2420/MG2520	\$1.80
CANON CL-31 1900B002	\$0.45
CANON CL-41 0617B002	\$0.45
CANON PG-240XL BLACK	\$0.90
CANON PG-240XXL BLACK 5204B001	\$0.90

HP

Part #	Value
HP #61 BLACK (CH561WN) (2014/03/31 EXPIRATION OR EARLIER)	\$0.45
HP #61XL BLACK (CH563WN) (2014/03/31 EXPIRATION OR EARLIER)	\$1.13
HP #61XL TRI-COLOR (CH564WN) (2014/03/31 EXPIRATION OR EARLIER)	\$1.35
HP 15 C6615DN	\$1.35
HP 22 C9352AN	\$1.35
HP 28 C8728AN	\$1.35
HP 45 51645A, C8842A	\$1.35
HP 51626A	\$0.45
HP 54 CB334AN	\$0.11
HP 57 C6657AN	\$1.35
HP 60 TRICOLOR CC643WN	\$0.90
HP 60 XL BLACK CC641WN	\$0.68
HP 61 BLACK CH561WN	\$0.45
HP 61 TRI-COLOR CH562WN (2014/04/01 EXPIRATION OR LATER)	\$1.13
HP 61 XL BLACK CH563WN	\$1.13
HP 61 XL COLOR CH564WN	\$1.35
HP 62 BLACK C2P04AN	\$0.56
HP 62 COLOR C2P05AN	\$1.01
HP 62XL BLACK C2P06AN	\$1.01

HP Q1339A SERIES 4300	\$1.80
HP Q5942A SERIES 4250/4350	\$1.80
HP Q5942X SERIES 4250/4350	\$1.80
HP Q6511X SERIES 2420	\$1.35
HP Q7516A SERIES 5200	\$1.13
HP Q7570A SERIES M5025/M5035	\$1.13
HP RG5-5681 FUSER	\$1.00

LEXMARK

Part #	Value
LEXMARK E260 FUSER ASSEMBLY 110-120 VOLT	\$1.00
LEXMARK MS310 (50F0HA0)	\$1.35
LEXMARK MS710 (52D1000)	\$1.35

HP 62XL COLOR C2P07AN	\$1.46
HP 701 CC635A	\$0.23
HP 95 8766W	\$0.23

LEXMARK

Part #	Value
LEXMARK 1 18C0781	\$0.34
LEXMARK 16 10N0016, DELL A920 T0529, SHARP UX-C70	\$0.11

PITNEY BOWES

Part #	Value
PITNEY BOWES 787-1	\$0.45